



INSPECTION REPORT

PROPERTY INSPECTIONS ELEVATED™





DRONE INSPECTION REPORT

07/31/2019

PROPERTY INFORMATION

CLAIM NUMBER Test Scan

TYPE OF LOSS

Hail

POLICY NUMBER


Test Scan

PHONE NUMBER

N/A

EMAIL ADDRESS

N/A



FLIGHT INFORMATION



PHOTO LOCATIONS FROM SCAN

ABOUT THIS REPORT

TOTAL IMAGES IN REPORT DATE REPORT CREATED 27 08/01/2019

13 IMAGES ADDED TO THE REPORT

TOTAL NUMBER OF ANNOTATIONS
5

PILOT IN COMMAND Scott Northrop

DRONE ID NUMBER TOTAL FLIGHT TIME

163DFBW0019EP3 00:11:01 START TIME END TIME

10:13 MDT -0600 10:24 MDT -0600








Photo Added by Scott Northrop 08/01/2019 3:14 PM MDT

Additional Notes

No additional notes have been added.





PROPERTY INSPECTIONS ELEVATED™

☎ AT002

Photo Added by Scott Northrop 08/01/2019 3:14 PM MDT

Additional Notes

No additional notes have been added.







™ LM015

Photo Added by Scott Northrop 08/01/2019 3:06 PM MDT

Additional Notes

No additional notes have been added.





DC008

Confirmed Damage	Count
Hail Hit	140
Rust (beta)	9
Soft Metal Damage (beta)	14







■ DC008-1 HAIL


Annotated by Scott Northrop 08/01/2019 3:04 PM MDT

Additional Notes

Scott Northrop 08/01/2019 3:04 PM MDT

Sample Hail Hits North West Slope







PROPERTY INSPECTIONS ELEVATED™

■ DC005-1 HAIL

Annotated by Scott Northrop 08/01/2019 12:07 PM MDT


Additional Notes

Scott Northrop 08/01/2019 12:07 PM MDT

Sample Hail Hit SE Slope







■ DC006-3 HAIL


Annotated by Scott Northrop 08/01/2019 4:08 PM MDT

No additional notes have been added. Additional Notes











■ DC006-2 HAIL

Annotated by Scott Northrop 08/01/2019 4:07 PM MDT

Additional Notes

No additional notes have been added.